

REPUBLIKA NG PILIPINAS

Pambansang Korporasyon Sa Elektrisidad

(NATIONAL POWER CORPORATION)

SMALL POWER UTILITIES GROUP - MINDANAO

## **PURCHASE ORDER**

DATE:

P.O.

Page 2

July 24, 2023

008603(SVP)

of 2

This PO number must appear on

all papers, invoices, packing list

and correspondence.

TO:

BULIZMANN IKADING

No. 43 Lupo Diaz St., Bo. Obrero, Brgy. 16-B Poblacion District, Davao City

Tel No. (082) 282-3310

PD NO.:

S3-SPUGM23-007

PR DATE:

DELIVER PERIOD: WITHIN 30 CALENDAR DAYS

FROM DATE OF RECEIPT OF THIS ORDER

TERMS: 30 DAYS UPON DELIVERY AND SUBMISSION OF ALL DOCUMENTS

STATED AT THE BACK HEREOF / COD / PREPAYMENT

DELIVERY POINT:

PLANT SITE - PDPP

REQUISITIONER:

J. A. DUHIG / Plant Head, PDPP

PO ITEM NO.	PR NO./ ITEM NO.	DESCRIPT	ION	QTY	UNIT OF	UNIT PRICE (P)	AMOUNT (P)		
		S3-PLM23-026 (02/0	8/2023) (67/-2	1 1	LOT		90 E2E 7		
		REQUEST FOR SERVICES: S	UPPLY LABOR.		-0.	strin in Mini	80,535.71		
		MATERIALS, EQUIPMENT & E				a shared the MARKET			
99 ≏ −		THE REPAIR OF GENSET STA				A. Jack Market			
5	1	REPAIR OF STARTER MOTOR	50,178.57						
		SCOPE OF WORKS:	537	00,170.07					
		1. CHECK UP THE ELECTROMA		ILS AND	HOUSING				
		2. CHECK UP THE ROTATING AF		5. REPLA	ACEMENT	OF BEARING			
		3. REPLACEMENT OF SOLENOID							
11	aran en la	4. REPLACEMENT OF VINTEX G	EAR	anney.		1 W 1966 111 may 1			
6	2	REPAIR OF WATER PUMP					30,357.14		
		SCOPE OF WORKS:		10 (10 E)	01 00 m	grafi (100 mily)	00,007.14		
		1. PRESS OUT THE SHAFTING, BUSHING & BEARING 4. ASSEMBLE THE WATER							
	F . O. I	2. CLEANING THE HOUSING OF	THE WATER PUN	IP .		HAFTING, BUSHING			
143	14.5	3. REPLACE THE REPAIR KIT		L DE DETE		1 1 1 1 1 1 1 1 1 1 1			
		S3-PLM23-027 (02/08	8/2023) 47/-3	n 1	LOT	or a transfer and transfer	87,839.29		
7	1	REQUEST FOR SERVICES: SI	UPPLY LABOR,	MATERIA	ALS.		71,000,20		
	WINDOWS TO	EQUIPMENT & EXPERTISE FOR THE REPAIR OF RADIATOR REPAIR OF ONE (1) UNIT RADIATOR FOR 260KW DALE PERKINS							
		SCOPE OF WORKS:			the deal	velice of the control			
	100 8	1. PULL-OUT OF RADIATOR FRO	M ENGINE.	time de	7. REPAIN	ITING OF RADIATOR	ray.		
1 - 2 - 2		2. TRANSPORT FROM PLANT TO SHOP. 8. DELIVER FROM SHOP							
1	п п п 'в	<ol><li>DISMANTLE ITS FRAME, UPPE</li></ol>	IIT						
- 1		4. OVERHAUL ALL TUBES, FINS				1	-2015 CIRD		
1		5. CUT AND REPLACE ALL DEFE		ID FINS	30 - 1	lacif in a memora			
		6. ASSEMBLE RADIATOR AND C	SI DDECCI IDE						
1	100850		1			ONE AT LEAST 20FG	DIFNESSURE.		
	1 H II V H DEL	NOTE: WARRANTY OF THE REP	AIRED RADIATOR	SHALLE	RE AT LEAS	STONE (1) VEAR	a constanting a		
	880 F WE F	Some seeds on a mark that	(25 10 (5)) (10)			P P	400 075 00		
			y ig track is	Subtota		P	168,375.00		
			Alia a mitte ege	Cubinda	/ / / / / / / / / / / / / / / / / / / /	4-60)	+		
	-		77.000 B			e 1 of 2)P	155,357.14		
	1 - 2 - 1		2 m 220 m - 1			P	323,732.14		
	1					Р	38,847.86		
DITIONAL	ا TERMS & CO	NOTION		IUIAL	AMOUNT.	Р	362,580.00		
		nied with Certificate of Warranty.	result in on		1000				
		ty shall be required either by retention money	or execial beat and		4				
		(5%) of the contract price.	or special bank guaranti I	æ	10 PA.				
squivaler ( (	I rive percent	R IS SUBJECT TO THE TE							

CC GL OE WO JO
61,83067 172 671-30

Pambansang Korporasyon Sa Elektrisidad

Please signify your acceptance and agreement with this P.O. By signing below:

FUNDS AVAILABLE

YAHOOB H. DARAYAN

CONFORME: GIANU MAY POSITION: CHO. MAY MAY DATE: 7/27/27/

ANNABELLE E. OGA

Financial Specialist 7.25.23

Department Manager, SPUG-MOD AUTHORIZED SIGNATURE

Office Address: NPC SPUG MINDANAO OPERATIONS DEPT.
NPC Mintal Complex, Kumintang St., Mintal, Tugbok dist., Davao City

Tel. Nos. (082) 293-0657 & 293-0610

## FOWER CONSORATE

REPUBLIKA NG PILIPINAS

Pambansang Korporasyon Sa Elektrisidad (NATIONAL POWER CORPORATION)

**SMALL POWER UTILITIES GROUP - MINDANAO** 

## PURCHASE ORDER

TO:

**BOLTZMANN TRADING** 

No. 43 Lupo Diaz St., Bo. Obrero, Brgy. 16-B Poblacion District, Davao City Tel No. (082) 282-3310 DATE:

P.O.

Page 1 of 2

and correspondence.

July 21, 2023

008603(SVP)

This PO number must appear on

all papers, invoices, packing list

PD NO.: PR DATE: S3-SPUGM23-007

DELIVER PERIOD: WITHIN 30 CALENDAR DAYS FROM DATE OF RECEIPT OF THIS ORDER

TERMS: 30 DAYS UPON DELIVERY AND SUBMISSION OF ALL DOCUMENTS STATED AT THE BACK HEREOF / COD / PREPAYMENT

REQUISITIONER:

PLANT SITE - PDPP

DELIVERY POINT:

J. A. DUHIG / Plant Head, PDPP

PO	PR NO./	DESCRIPT	LON	OTV	UNIT OF	LIMIT DDIOE (D)					
TEM NO.	ITEM NO.	adversion and the state of the same and the	age of the second	QTY	MEASURE	UNIT PRICE (P)	AMOUNT (P)				
		REQUEST FOR SERVICES:		1	LOT		362,580.0				
		LABOR, MATERIALS, EQUI		2 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	djuga u gra ovratek mar	or - E. (17.5), (16)	GA CHASTON				
100		EXPERTISE FOR THE REPARTS INTEN	AIR OF GENS	ET	222	and such dark a					
		S3-PLM23-025 (02/0									
	in adjusti,	REQUEST FOR SERVICES: S			LOT	pank k S SigN =1 +	155,357.1				
		MATERIALS, EQUIPMENT AN									
	Parago of	THE REPAIR OF GENSET DE			1= =	70 - 51.0					
1	1	REPAIR OF CYLINDER HEAD	CUMMINS	1	The state of the s		39,285.7				
		SCOPE OF WORK:		ir ya ba	1 = 2 % Q hr	other medical	00,200.7				
		CYLINDER HEAD CRACK TEST VALVE SEAT RI				REFACE/SETTINGS					
11		CYLINDER HEAD RESURFA	VALVE G	SUIDE REP	PLACE						
		VALVE SETTING		ASSEME	LE/ADJUS	T CLEARANCE					
2	2	REPAIR OF FAN HUB CUMMIN	NS	and the string of		Many - ran in	15,178.5				
1 1 1 1 1	and the second	SCOPE OF WORK:		P. Sylving	grada n	for more of surger					
1 2.5	Arten Se	REPLACE BEARING		The state of the	Anna Tan	Menin skin i i i i i i i i i i i i i i i i i i					
	lad La	MACHINING OF BEARING SI	HAFTING AND H	UB		Biggs 1 20 1					
		FABRICATION OF SPACER			No. 6						
3	3	REPAIR OF OIL PUMP OF 275	KW PERKINS	1	John William	the fig. 10 to	30,357.14				
	-acil i mid	SCOPE OF WORK:			TO THE STATE OF						
	minter ac-	-REMOVE ALLPUMP HOUSIN	G								
	1190	-SEPARATE THE OIL PUMP HOUSING FROM THE OIL PUMP COVER									
		-CHECK THE RADIAL CLEARANCE BETWEEN INNER ROTOR & OUTER ROTOR OF THE OIL PUMP									
		-CHECK THE AXIAL CLEARANCE BETWEEN THE OIL PUMP HOUSING AND THE OUTER ROTOR									
277	N 88 10g	-CHECK THE TWO INNER A	ND OUTER ROT	FORS AND	THE OIL P	UMP HOUSING					
		-REPAIR AND MACHINING	GEAR	-INSTAL	L THE OIL	PUMP COVER					
	neg is nest i	-REPLACE BUSHING		-INSTAL	L THE OIL	PUMP HOUSING					
4	4	REPAIR OF TURBO CHARGEF	RPERKINS	The second of th		aga marin yakin menga	70,535.71				
		SCOPE OF WORK:		and the same		are anti-post sure selec-					
61 S. Se al		-STANDARD & BALANCING OF IMPELLER SHAFT -CHECK-UP & RE-STANDARD OF CENTER HOUSING -REPLACEMENT OF ALUMINUI									
		-CHECK-UP & RE-STANDARI	OF TURBINE	HOUSING	The second second second second	EMENT OF TURBO CI					
DITIONAL	TERMS & CO	-CHECK-UP & RE-STANDARI	OF INTAKE HO	DUSING	-ASSEME						
Delivery sha	ll be accompa	nied with Certificate of Warranty.			25.41.11	S 1/ _ 15 1 M					
Upon accept	ance, a warar	ty shall be required either by retention money	or special bank guara	ntee	Simple of						
		(5%) of the contract price.	A STATE OF		l	Р	155,357,14				
	110 0 00	ER IS SUBJECT TO THE TE			RINTED		,				

66830G7, 1/2 G7/~30

BY

Please signify your acceptance and agreement with this P.O. By signing below:

ANNABELLE E. OGA

YAHCOB H. DARAYAN
Department Manager, SPUG-MOD
AUTHORIZED SIGNATURE

CONFORME: (NAME), NOW MARKED POSITION: (DE) / MONKEY
DATE: 7/27/23

Office Address: NPC SPUG MINDANAO OPERATIONS DEPT. NPC Mintal Complex, Kumintang St., Mintal, Tugbok dist., Davao City

Tel. Nos. (082) 293-0657 & 293-0610